F-CITYLIGHT



Seattle Cement Plant 3801 E. Marginal Way South Seattle, Wash. 98134

August 3, 1982

Mr. Kerry Packard, P.E. Electric Service Engineer Seattle City Light 1015 Third Avenue Seattle, Washington 98104

Dear Mr. Packard:

Attached for your information is a report of dissolved gas analysis for the 26/4.16 KV master_substation transformer. The Seattle City Light transformer was included in a plant-wide analysis of transformer condition by Transformer Consultants.

Please note that a very minor deterioration of the transformer oil was detected and a 6-month retest is recommended. Lone Star Industries will not be pursuing this transformer further.

Very truly yours,

Kenneth J. Rone, Jr. Assistant Plant Manager

Engineering & Maintenance

KJR/mme Attachment

cc: T. G. Wells

USEPA SF

1261052